

Oil Field Environmental Incident Summary

Incident: 20150219160805 **Date/Time of Notice:** 02/19/2015 16:08

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 2/19/2015

Time Incident: 13:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 18

Qtr:

Location Description: BLUE BUTTES COMPRESSOR STATION: approximately 18 miles due east of Watford City, ND just off Hwy 23 on the north side of the road.

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	20	Gallons	20	Gallons		

Description of Other Released Contaminant:

Natural Gas Liquids (Condensates)

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this event.

Areal Extent:

The contents were contained inside the lined secondary containment structure.

Potential Environmental Impacts:

There were no adverse environmental impacts

Action Taken or Planned:

The spill was contained inside the lined secondary containment structure.

Wastes Disposal Location: Impacted soils will be transported to a licensed landfill.

Agencies Involved:

Updates

Date: 2/20/2015 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Small release from tank overflow inside lined tankage containment structure. No on-site inspection necessary at this time.